

Work Order

#48052



Service Provider: Vehicle Pool 1001 W Center St Manteca, GA 95337	Customer (# 60): Police Department 1001 W. Center Street Manteca, CA 95337 (209) 456-8153
---	--

Unit ID	Fleet	Group	Equipment Make	/ Equipment Type
60 6126	60	VEH	NISSAN	4 X 2 PICKUP
License#	State	Year	VIN Serial Number	Equipment Model
29543L 1	CA	2011	1N6AA0ED0BN312576	NISSAN 4DR PiU
Engine Size	Driver's Name		Driver's Phone	IWO Author
				12546
Hazardous Materials:	0.00	Start:	11/12/2024 05:44:00	
Other:	0.00	End:		
Parts:	50.61	Down Time:		
Outside Work:	78.00	Odometer-M Reading:	146,902	
Labor:	1,303.17	Repair Site:	Vehicle Maintenance	
		Repair Class:	PREVENTIVE MAINT	
		Labor Hours:	12.5000	
Sales Tax:	0.00	Avg Labor Rate:	104.25/Hr	
Other Tax:	0.00			
Total Cost:	1,431.78			

NOTES:

2546 - 11/13/2024 8:16:35 AM

2546 ,.. 11/13/2024 8:01 :22 AM

REPLACE FRONT SHOCKS. (1.0)

REPLACE REAR SHOCKS. (1.0)

REPLACE OIL SENDING UNIT .IT LEAKS (1.5)

REPLACE SWAYARM BUSHINGS. (1.0)

REPLACE FRONT ROTORS AND BRAKES PADS. (1.5)

REPLACE REAR BRAKE ROTORS AND PADS. (1.5)

DUE FOR 8 SERVICE.(2.0)

CHECK TIRES FOR WEAR/ REPLACE ALL FOUR TIRES (2.0)

NOTES {continued}!

OIAG FRONTSHAKES AT HIGH SPEEDS/ BAO TIRES (.5)

Services

SERVICE DESCRIPTION	Budget	PM?	REASON	DATE	MECHANIC	HOURS	RATE	COST	Otw
DIAGNOSIS	0.00	N		11/11/2024	1001	0.1000	104.25	52.13	
4 WHEEL ALIGNMENT	0.00	N		11/12/2024	NONE	0.0000		0.00	i6D'I
BRAKE PADS, FRONT.	0.00	N	FAI	11/12/2024	1001	1.0000	104.25	104.25	
REPAIR/REPLACE	0.00	N	FAI	11/12/2024	1001	1.0000	104.25	104.25	
SHOCK, FRONT, REAR, REPLACEMENT	0.00	N	FAI	11/12/2024	1001	1.0000	104.25	104.25	
FRONT, AXLE 1	0.00	N	FAI	11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N	FAI	11/12/2024	1001	0.5000	104.25	52.13	
H01 (H.S.) AXLE 2	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
GAUGE, OIL PRESSURE	0.00	N		11/12/2024	1001	1.5000	104.25	156.38	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	2.0000	104.25	208.50	
SHOCK, LEFT AXLE 1	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
SHOCK, LEFT AXLE 2	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
SHOCK, RIGHT AXLE 1	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
SHOCK, RIGHT AXLE 2	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
SWAY ARM BUSHING	0.00	N		11/12/2024	1001	1.0000	104.25	104.25	
REPAIR/REPLACE	0.00	N		11/12/2024	1001	0.5000	104.25	52.13	
INSPECT TIRES FOR WEAR	0.00	N	SC	11/12/2024	1001	0.5000	104.25	52.13	
TIRES, 8&R SET	0.00	N	FAI	11/12/2024	1001	2.0000	104.25	208.50	

Parts

PART DESCRIPTION	PART ID	UOM	QTY USED	UNIT COST	EXT. COST
OIL FULL SYNTHETIC BULK 5W30 W/ 10W	5W30-S	Gal	2.00	18.39	36.78
LF3t37fLG 1" H TEFH Oil	ACP 1FZ011/	EA	1.00	4.91	4.91
FILTER AIR	1.1nBA,n	EA	1.00	8.92	8.92



Main: 209-307-9260 Fax: 209-307-9261

DISCLAIMER OF WARRANTY: ALL PARTS AND ACCESSORIES ARE SOLD BY OUR DEALERSHIPS AS IS. OUR DEALERSHIPS DISCLAIM ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, IN CONNECTION WITH THE SALE OF PARTS AND ACCESSORIES. THE ENTIRE RISK AS TO THE QUALITY AND PERFORMANCE OF THE VEHICLE AND PARTS AND ACCESSORIES IS WITH THE CUSTOMER AND, IF APPLICABLE, THE MANUFACTURER. IF THE VEHICLE OR ANY INSTALLED PARTS OR ACCESSORIES SHOULD PROVE DEFECTIVE FOLLOWING THEIR PURCHASE, THE CUSTOMER AND POSSIBLY THE MANUFACTURER AND NOT THE DEALERSHIP ASSUME THE ENTIRE COST OF ANY NECESSARY SERVICING OR REPAIR. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS INVOICE APPLIES ONLY TO PARTS INSTALLED AND/OR REPAIRS PERFORMED BY OUR DEALERSHIP. THE DEALERSHIP NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PARTS OR PRODUCTS. THIS DISCLAIMER IN NO WAY AFFECTS THE PROVISIONS OF ANY MANUFACTURER OR SUPPLIER WARRANTIES.

**S
O
I
D
T
O**

SHIP
TO

CITY OF MANTECA
1001 WEST CENTER ST
MANTECA, CA 95337

SHIP VIA		r/LNO.		TON CA	
		PART NO.	DESCRIPTION	LIST	NET AMOUNT
	0	TBILL-06686	TEST MICHELIN	326.00	300.00 1,200.00
	0	DA06M-9FEOPNW	II PAD KIT	95.00	76.80 76.80
	0	DD06M-ZC02PNW	PD KIT	96.00	76.80 76.80
	0	Part number DD06M-ZC02P.NW	replac	8s	DD06M-Z
	0	D0206-ZR01CNW SE	ROTOR DI	106.00	84.80 169.60
	0	D3206-7SOOCNW	ROTOR-DI	106.00	84.80 169.60
	0	25240-4M40E	SWITCH A	35.40	28.32 28.32
	0	999MP-1217HP 85D4	THREEBON	16.99	13.59 13.59
	0	E6C10-7832PNW	ABSORBER	156.78	125.42 250.84
	0	S4618-7S000	BUSHING	10.38	8.30 16.60
	0	S4618-7S000	ROD ASSY	81.78	65.42 130.84
1N6AAOEDOB N312576					
ALL PARTS 2-3 DAY ETA					
OIL PA. DOES NOT USE GASKET ONLY NISSAN SILICONE ***					
**** I N V O I C E Q U O T E - DO NOT PAY ****					
*****PARTS DIRECT PHONE***** *****209-307-9273*****				PARTS 2,132.99	
WE APPRECIATE YOUR BUSINESS!				SUBLET	
NO RETURNS ON SPECIAL ORDER OR				FREIGHT 0.00	
ELECTRIC.AL PARTS				SALES TAX 191.97	
CUSTOMER'S SIGNATURE				TOTAL \$2,324.96	

DealerCAF 2014 CDK Global, LLC FIFTH PARTS SERVICE GROUP, 27101 - "United Wayway", CA, 9096077

CUSTOMER COPY

6126 Nissan Titan

PARTS Needed

IBASULTO @ MANTECA.GOV

Mark